LANDSLIDE AND FLOOD SUSCEPTIBILITY MAP OF LARENA QUADRANGLE SIQUIJOR PROVINCE, PHILIPPINES



INDEX MAP

LEGEND :

High Susceptibility to Landslide

Areas with high landslide susceptibility rating have active/recent landslides and tension cracks that would directly affect the community. Those with steep slopes and drainages that are prone to landslide damming are also highly susceptible to landslides.

Moderate Susceptibility to Landslide

Areas with moderate landslide susceptibility rating have inactive/old landslides and tension cracks which are located away from the community. These areas usually have moderate slopes.

Low Susceptibility to Landslide

Areas with low to gentle slopes and lacking tension cracks have low landslide susceptibility rating.

High susceptibility to flooding

Areas with greater than 1 meter flood height. These areas are usually flooded for several hours during heavy rains; include landforms of topographic lows such as active river channels, abandoned river channels and areas along river banks; also prone to flashfloods.

Low to moderate susceptibility to flooding

Areas with less than 1.0 meter flood height. These are usually inundated during prolonged and extensive heavy rainfall or extreme weather condition

Roads
River
Municipal boundary
Barangay center location

N
W E
S

0 1.5 3
kilometers

TRANSVERSE MERCATOR PROJECTION
MAPPING SCALE 1:50, 000

GIS Processing :
Lands Geological Survey Division

Data Sources:
MGB Geohazard Assessment Team
Geological Database and Information Systems Section
Lands Geological Survey Division
Geosciences Division MGB RO VII

Base Map :
Sheet No. 3647 I "Larena Quadrangle"

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
MINES AND GEOSCIENCES BUREAU
LANDS GEOLOGICAL SURVEY DIVISION

All Rights Reserved (2010)

LANDSLIDE SUSCEPTIBILITY MAP OF LAZI QUADRANGLE
SIQUIJOR PROVINCE, PHILIPPINES



INDEX MAP

LEGEND :

High Susceptibility to Landslide

Areas with high landslide susceptibility rating have active/recent landslides and tension cracks that would directly affect the community. Those with steep slopes and drainages that are prone to landslide damming are also highly susceptible to landslides.

Moderate Susceptibility to Landslide

Areas with moderate landslide susceptibility rating have inactive/old landslides and tension cracks which are located away from the community. These areas usually have moderate slopes.

Low Susceptibility to Landslide

Areas with low to gentle slopes and lacking tension cracks have low landslide susceptibility rating.

Low to moderate susceptibility to flooding

Areas with less than 1.0 meter flood height. These are usually inundated during prolonged and extensive heavy rainfall or extreme weather condition

Roads

River

Municipal boundary

Barangay center location

N
W E
S

0 1.5 3
kilometers

TRANSVERSE MERCATOR PROJECTION

MAPPING SCALE 1:50, 000

GIS Processing :
Lands Geological Survey Division

Data Sources:
MGB Geohazard Assessment Team
Geological Database and Information Systems Section
Lands Geological Survey Division
Geosciences Division MGB RO VII

Base Map :
Sheet No. 3747 III "Alba Quadrangle"

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
MINES AND GEOSCIENCES BUREAU
LANDS GEOLOGICAL SURVEY DIVISION

All Rights Reserved (2010)

LANDSLIDE AND FLOOD SUSCEPTIBILITY MAP OF MARIA QUADRANGLE SIQUIJOR PROVINCE, PHILIPPINES



INDEX MAP

LEGEND :

High Susceptibility to Landslide

Areas with high landslide susceptibility rating have active/recent landslides and tension cracks that would directly affect the community. Those with steep slopes and drainages that are prone to landslide damming are also highly susceptible to landslides.

Moderate Susceptibility to Landslide

Areas with moderate landslide susceptibility rating have inactive/old landslides and tension cracks which are located away from the community. These areas usually have moderate slopes.

Low Susceptibility to Landslide

Areas with low to gentle slopes and lacking tension cracks have low landslide susceptibility rating.

Low to moderate susceptibility to flooding

Areas with less than 1.0 meter flood height. These are usually inundated during prolonged and extensive heavy rainfall or extreme weather condition

Roads

River

Municipal boundary

Barangay center location

N
W E
S

0 1.5 3
kilometers

TRANSVERSE MERCATOR PROJECTION

MAPPING SCALE 1:50, 000

GIS Processing :
Lands Geological Survey Division

Data Sources:
MGB Geohazard Assessment Team
Geological Database and Information Systems Section
Lands Geological Survey Division
Geosciences Division MGB RO VII

Base Map :
Sheet No. 3747 IV "Maria Quadrangle"

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
MINES AND GEOSCIENCES BUREAU
LANDS GEOLOGICAL SURVEY DIVISION

All Rights Reserved (2010)